NOTES: 1. INSTALLATION MU: ELECTRICAL CODE	IST BE IN ACCORDANCE WITH NATIONAL AND LOCAL							
	ECTED EQUIPMENT REQUIRES A NEUTRAL, THE NEUTRAL DULD BE FULLY CAPACITY SIZED.							
	ND AC OUTPUT CABLES MUST BE RUN IN SEPARATE					1		
	IND CONTROL WIRING MUST BE RUN IN SEPARATE		1			ĺ		
5. EQUIPMENT GROU	JND/PROTECTIVE EARTH CONDUCTORS AND CONNECTIONS FALLED FOR PROPER OPERATION.	! 	! 			i I		
	ISE NOTED, ALL POWER CABLES MUST BE SUITABLE O' C AND MUST BE COPPER CONDUCTORS ONLY.		 			I I		
						l		
		<u>.</u>	i			i		
			— — — 			, 		
		1	 			1		
			<u> </u>			1		
						[
						[
			1			1		
			i I			i		
		I I	 			! 1		
	. — — — — — —							
						1		
		I	I			i		
		! !	! 			 		
			1			1		
						1		
			1			1		
						i		
		I I	I 			1		
DRAWN BY	SHEET NO.			<u> </u>			<u> </u>	
K. STACY CHK BY	1 OF 1	ONE LINE BLACK CONTROL						
G. FUNK REF. DWG.	ECN NO.	ONE-LINE DIAGRAM NOTES LIEBERT APS UPS			15		ODW DDW5	VERTIV
REF. DWG.	ORDER NO.			DWG. NO. APS2000	DATE 8/19/13	REV. # 1050 DEARBO P.O. BOX COLUMBUS, O	OKN DRIVE 29186 OHIO 43229	·
				FILE NAME:				